DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Casey, William **Report No:** WIR-027788 Address: 333 Burma Road **Date Inspected:** 15-Jun-2012

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 730 **OSM Departure Time:** 1600 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Location: Pier 7 Job Site Contractor: American Bridge/Fluor Enterprises, a JV

CWI Name: N/A**CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** S.A.S. Components

Summary of Items Observed:

The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI reviewed contract documents at pier 7. The QAI used approved weekly welding report submittals and cross referenced the welding and inspection status as reported with QA records to identify the overall weld status.

The QAI continued checking punch listed items for status / verification. This work was in progress until the end of the shift. See the list of items checked and attached photos.

Other item # 17, all are welded and inspected by QC, not painted yet.

PL # 839 - welding in progress

PL # 3479 / 3480 - welded and painted

PL # 3582 - cover plates waiting to be installed

PL # 3730 - unable to verify from bottom of trestle

PL # 3760 - cover plates not installed yet, may have additional bolting access issues at luminaire bases


WELDING INSPECTION REPORT

(Continued Page 2 of 2)









Summary of Conversations:

The QAI relayed the status of the document reviews to the QAI Lead Bill Levell. The QAI relayed the punch list items observed to the ASMR Parinaz Aghili. Except as described above, there were no other notable conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy, (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By:	Croff,Scott	Quality Assurance Inspector
Reviewed By:	Levell,Bill	QA Reviewer